NOTIFIER® by Honeywell

ONYX Series Version 31.02.01 Firmware Release Notes

September 2024

NFS2-3030/NCA-2 31.02.01/LCM 19.01.02 is the latest firmware version and includes the following modifications:

- Fixed an issue with the Wenlock Control Module where the module would inadvertently be placed into an ON/OFF pattern mode when activated rather than the expected constant ON mode

Requirements:

- Version 31.01.02 is the latest release of firmware and requires VeriFire Tools version 12.45 or higher
- The panel and the loop cards need to be upgraded

NOTIFIER® by Honeywell

ONYX Series Version 31.02.01 Firmware Release Notes

Previous Version

May 2022

NFS2-3030 version 31.01.02 is the latest production firmware version and includes the following modifications:

- Support for FSAE functionality for the following FSAE Type codes on FCO-951 detector:
  - Fire/CO FSAE1
  - Fire/CO FSAE2
  - Fire/CO FSAE1 (CO SUP)
  - Fire/CO FSAE2 (CO SUP)
- As part of Cyber Security upgrades, this firmware V31.01.02 will trigger an error message if the user continues to use the panel's default password.

Requirements:

- Version 31.01.02 is the latest release of firmware and requires VeriFire Tools version 12.10 or higher
- Recommended firmware versions for ONYX series panels on NOTI-FIRE-NET with version 31.01.02 panels:
  - NFS2-3030 version 31.01.02
    - LCM-320 version 19.0.12
    - LCD-160 version 12.0.06
  - NCA-2 version 31.01.02
    - LCD-160 version 12.0.06
  - NCM-PCA version 3.60.6
  - NCM-PCB version 10.3.1
  - HS-NCM-PCA version 20.5.9
  - HS-NCM-PCB version 30.16.1
  - HS-NCM-W2 version 31.00.46
  - DVC version 8.11.5 o DAA version 003.070.001
    - DAA2 version 001.090.001
    - DAX version 001.030.001
    - DS-DB version 001.050.001
    - DS-AMP version 001.001.001
  - ONYXWorks version 4.64
- Note: The support for FSAE Type code on ONYXWorks, CLSS Gateway, NCD & INSPIRE Series will be included in a future release.

June 2022

NFS2-3030 version 029.01.01 is the latest production firmware version and includes the following modifications:

- LCM improvement to address intermittent FDM issues
- Cyber Security enhancements

NCA-2 version 29.01.01 is the latest production firmware version and includes the following modifications:

- Cyber Security enhancements